	s x	OFFICE OF THE SOLICITOR GI 134 Amorsolo St., Legaspi Vi Makati City				
		PURCHASE ORD	ER			
Supplier:	VALLEY S	SOUTH MOTOR WORKS	P.O. #	023-02-020		
Address:	667 San A	ndres St., Malate, Manila	Date:	February 1	5, 2023	
TIN: 175-722-874-000			Mode of Procurement: Small Value			
Account No: 3401-1349-71 Bank: LBP - Malate			Procurement 53.9			
Telephone:				1100010		
Gentlemen:		x				
		this Office the following articles subject to the terms and conditions				
Place of Delivery: OFFICE OF THE SOLICITOR GENERAL				Delivery Term:. w/in 30 days upon receipt of P.O.		
Data of Dalia	10.70.11		Payment	Term: w/in 30 days upon		
Date of Deliv Stock No.	Unit	Description		Bank to ban Unit Cost	Amount	
SIUCK INU.	Unit		Qty.	Unit Cost	Amount	
×.		DIAGNOSIS, SUPPLY, LABOR AND MATERIALS FOR REPAIR OF DEFECTIVE AIRCON SYSTEM IN OSG SHUTTLE BUS FOR VEHICLE MODEL 2010 HINO BUS FG1JPUZ WITH PLATE NO. SKL 815				
	Lot	Scope of Works: For General Cleaning of Aircon System For Replace of Defective Parts Estimated Material Quantities (but not limited to): Nitrogen and Degreaser 2 liters Compressor Oil Full Charge of Freon Gas 134-A 1 pc Drier Warranty: 3 months	1	Php 35,850.00 Vat Inclusive	Php 35,850.00	
Total Amoun	t in Words:	Thirty Five Thousand Eight Hundred Fifty Pesos Only	I,	J	Php 35,850.00	
In case of failure to make the full delivery within the time specified above, a per delay shall be imposed. Conforme:				nalty of one-tenth (1/10) of one percent for every day of Very truly yours JESSICAL. CASTRO CAO, Administrative Division EDITHA R. BUENDIA Director IV, HRMAS		
Funds Availa	A	02 -10/10/-2023 -02-066 ALOBS: Amount! RIEL J. UBIÑA hief Accountant				