Republic of the Philippines

OFFICE OF THE SOLICITOR GENERAL

134 Amorsolo St., Legaspi Village Makati City

		PURCH	IASE ORDER						
Telephone: Gentlemen:	20th Floor 004-662-29 : 9661-0062- 8683-6800	Bank: BPI - EDSA Br Bank Location 2279 Pasons	'anch Tamo Extension, Makati City	P.O. # 023-10-163 Date: October 20, 2023 Mode of Procurement: Direct Contracting					
Please furnish this Office the following articles subject to the terms and conditions contained herein Place of Delivery: OFFICE OF THE SOLICITOR GENERAL					Delivery Term: w/in (30) working days upon receipt of P.O				
Date of Delivery					Payment Term: within 30 days upon final inspection and acceptance (Bank to Bank)				
Stock No.	Piece Piece Piece	Diagnosis, Supply of Labor and Materials for the Elevator 2 located at OSG Building, including distinstallation, with the following specifications: Initial Diagnosis: a. Passenger Elevator 2: For Supply and Replace VVVF, Plastic Guide Below, and Concentric Whe Supply and Installation of Various Parts for PE2 Set Motor VVVF Plastic-Guide Below (Car Door Guide Shoe) Concentric Wheel D=48	mantling and sement of Set Motor	Qty.	Php	59,000.00 2,500.00 4,000.00	Php Php Php	59.000.00 10.000.00 16,000.00 85,000.00 10,200.00 95,200.00 4,760.00	
Total Amount in Words. Ninety Thousand Four Hundred Forty Pesos Only							Php	90,440.00	
In case of Conforme:	of failure to ma	ake the full delivery within the time specified above, a penalty	y of one-tenth (1/10) of one	percent fo		Very truly JESSICA L. AO, Administra	yours	٨	

Funds Available.

ALOBS: 02-/0/101-2023-11-743

\$ 90,440.00

EDITHA R. BUENDIA Director IV. HRMAS